








8151












8151N


NR	ELEMENT	8151N
E1	<div data-bbox="236 562 389 600">D8151_1N</div> <div data-bbox="477 315 580 573"></div>	1
E2	<div data-bbox="236 882 389 920">D8151_2N</div> <div data-bbox="477 633 580 891"></div>	1
E3	<div data-bbox="296 949 679 1149"></div>	1
E4	<div data-bbox="375 1294 633 1503"></div>	1



8151N

Nr	Element	DIN	ELEMENT	Σ
1		-	S6x60	6
2		-	W6x60	1
21		DIN 125	8x16	1
26		-	S4x40	32
48		-	TE_1_A2_g4_v1	4
50		-	TE_2_A2_g4_v1	4
77		-	K3_d30_A89_G	1
213		-	Z_NA_1	1
214		-	Z_NA_2	1



8151N



8151N



ENG: Due to the irregular shapes of natural robinia wood trunks, all dimensions provided in the documentation may slightly vary from the actual dimensions of the product.

PL: Z uwagi na nieregularne kształty naturalnych pni drewna robinii, wszystkie wymiary podane w dokumentacji mogą nieznacznie odbiegać od rzeczywistych wymiarów produktu.




1

8151 N




2

8151 N



INST_81_11
INST_81_17



3

8151N

B25 0,31m³

min. 48H

